



Form Ref: HSI-10

Independent Health & Safety Inspection – Blue Star Item

Version: 2.0 Jun 2015



Awarded for Exceptional Performance or New Initiative not widely used on other sites

Project	Principal Contractor (PC)	Date of Inspection
M3 J2-4a	Balfour Beatty	12/02/16
Site Contact	Email Address	Telephone Number

Description of Blue Star Item	Developed temporary signage to overcome the issue of the back of vehicles having non-metallic boots and bumpers This allows staff to use their hire car or their company on the network with the correct
Benefits of Blue Star Item	Chapter 8 without placing adhesive chevrons to the rear of the vehicles which can cause excessive costs for repairs from the hire and leasing companies upon return.
Details and Cost of any Specific Product	Each unit is costing approx. £200 per car
Photograph	HIGHWAY MAINTENANCE