

Form Ref: HSI-10

Independent Health & Safety Inspection – Blue Star Item

Version: 2.0 Jun 2015

 \star

Г


Awarded for Exceptional Performance or New Initiative not widely used on other sites

Project	Principal Contractor (PC)	Date of Inspection
A556 Knutsford to Bowdon	Costain	16/05/16
Site Contact	Email Address	Telephone Number

Description of Blue Star Item	RtB 10 – Communication of Risk. A Supervisor meeting is held at 16.00 each day to discuss the work that has taken place that day, and the work proposed for the following day, to identify any issues or potential clashes of work activity. An SoS Briefing document is then prepared listing the activities taking place at each area of the site, who the contractor is, what they are doing, the plant and people involved, planned deliveries, and a target of what is to be completed by the end of the week. The Briefing document also includes blue (instructions), red (issues) and green (positive feedback) SHE Information. There are also sections on Quality Observations and the Weather Forecast.
Benefits of Blue Star Item	The SoS seen for the day of the inspection also included Best Practice information on the use of coloured cones on site. The site has recently introduced an additional SoS 'Be Clear – Be Safe' Briefing page, which is to be completed by the Supervisor at the work area. This includes the activities proposed, the relevant RAMS and Permit references, and any significant risks. It also has a place to list any proposed deliveries, toolbox talks or safety alerts delivered, feedback from the workforce, and a 'Take 5' section with 5 questions to be answered before commencing work. An aerial picture of the site is displayed at each work area with 'You Are Here' marked on it, the proposed finished layout, key programme dates, key site rules, and radio channel details for different forms of communication on site. Hazard Boards are also displayed outside the welfare facilities at the main work areas on site.
Details and Cost of any Specific Product	









Data Classe	Date Closed						
Statement of the local division in the local	To Be actioned By	Structures	Costain	For Information	AI	Online Team	For Information
and the second se	tion	to capping near aned up	nt shift at road sues	eyhurst bridge	mpleted to a	ridge looks to be	during placement
	Quality Observat	Concrete pump discharging out on Blue Bridge – still has not been cle	Very poorly laid ducting during nigh crossing on roundabout causing is	Remedial actions ongoing to Bentl	Overall CBGM works look to be co good standard	Water proofing on Chester Road B going well	Capping can become segregated on - it should not have an open textur
I STATISTICS IN COMPANY	Date Raised	03/05/2016	03/05/2016	09/05/2016	09/05/2016		09/05/2016



