


<b>Form Ref:</b> HSI-10	<b>Independent Health &amp; Safety Inspection – Blue Star Item</b>	<b>Version: 2.0</b> Jun 2015
----------------------------	--	---------------------------------

	<b>Awarded for Exceptional Performance or New Initiative not widely used on other sites</b>
---	---

<b>Project</b>	<b>Principal Contractor (PC)</b>	<b>Date of Inspection</b>
M1 J19-16	Costain Galliford Try	15/09/16
<b>Site Contact</b>	<b>Email Address</b>	<b>Telephone Number</b>
Eamonn Slevin	<a href="mailto:Eamonn.slevin@costain.com">Eamonn.slevin@costain.com</a>	01788 520600

<b>Description of Blue Star Item</b>	<p>The M1 J19-16 contract implements a procedure whereby in order to work adjacent to the live traffic or across an open gap in the Zoneguard, there must be a physical barrier (temporary or permanent) in place or a closed lane separation in place.</p> <p>The picture to the right shows a gap in the Zoneguard filled with water filled barriers (Rhino).</p>
<b>Benefits of Blue Star Item</b>	<p>This system means a lower risk of vehicle incursions into the work site and is safer for the road worker.</p>
<b>Details and Cost of any Specific Product</b>	

**Photograph**



Gap in the Zoneguard filled with water filled barriers (Rhino)

**Photograph**



Additional sections of Zoneguard installed to infill access / exit to allow work to take place