

# Electricity Alliance



## The Subject - Breach of Golden Rules (North Hyde)

- Flatbed truck delivering concrete troughs for a contractor arrived on site before 08:00am
- Driver told where to park by security guard & requested to produce his paperwork for his Hiab
- Driver correctly parked in the Laydown area
- Driver was not given the delivery driver sheet from the gatehouse
- Driver subsequently seen on the back of the flatbed, around 4ft high, removing netting
- The driver alighted flatbed before the person observing incorrect WAH procedure could intervene



### •Key Learning Points

- Sites are reminded not to allow delivery drivers on to the site unless briefed and recipient of delivery is present at all times.
- If there is doubt, they are to be held at the gate or escorted to the area where they are to be off loaded, with instructions not to proceed until off loading team are present.
- All drivers are to be given a copy of the delivery driver's induction sheet and relevant safety information.
- Delivery RAMS are to be authorised by the Site Management Team and are to reference SEESA WAH procedure.
- Tool box talk to be given to all operatives and sub-contractors including security staff.

SHE BULLETIN

SHE BULLETIN