

HSSQ Alert Template

CORE/HSSQ/PRO/033-F001

Business:	Carillion Construction Services	ALERT
Title:	Mobile Elevated Work Platform - Failure	Reference No: CCS 180
Issue Date:	19 th November 2015	Issued By: Geoff Lee
Type of Alert:	Health & Safety	
Subject:	M40 MEWP failure	
Who is affected:	All operating this model of MEWP: VERSALIFT LAT-160-F	



Details:	<p>A recent incident occurred involving a Van mounted MEWP whereby the bucket tipped forward without any prior warning leaving the operative stranded and requiring rescue. The above photo shows the position of the bucket resting on the boom at 90 degrees. The operative was correctly harnessed and secured to the bucket at the time of the incident.</p> <p>The investigation continues as no immediate signs of mechanical failure have been identified.</p>	
Action Required:	Immediately - Suspend the use of all Van mounted Versalift LAT-160-F pending the outcome of the investigation	
Further Information:	N/A	
Original Source:	Carillion M40 Highways Project	
Method for confirming that actions have been taken:	Briefing records to be retained with project files	
Local Action Taken:	<< Contract Head to complete >>	