


Form Ref: HSI-10	Independent Health & Safety Inspection – Blue Star Item	Version: 2.0 Jun 2015
----------------------------	--	---------------------------------

	Awarded for Exceptional Performance or New Initiative not widely used on other sites
---	---

Project	Principal Contractor (PC)	Date of Inspection
M1 J19-16	Costain Galliford Try	15/09/16
Site Contact	Email Address	Telephone Number
Eamonn Slevin	Eamonn.slevin@costain.com	01788 520600

Description of Blue Star Item	<p>The M1 J19-16 contract implements a procedure whereby in order to work adjacent to the live traffic or across an open gap in the Zoneguard, there must be a physical barrier (temporary or permanent) in place or a closed lane separation in place.</p> <p>The pictures below shows a gap in the Zoneguard filled with water filled barriers (Rhino).</p>
Benefits of Blue Star Item	<p>This system means a lower risk of vehicle incursions into the work site and is safer for the road worker.</p>
Details and Cost of any Specific Product	

Photograph



Photograph

