




Safety Alert

Suspected Vandalism

20th March 2018

The following pages of this safety alert were issued by Highways England's supply chain partner:

BAM Nuttall and Morgan Sindall Joint Venture (BMJV)

Date:	19/03/2019	Time:	10:45am
Location:	M27 between Junction 7 – Junction 5		
Summary Description (<i>Factual description only, opinions and assumptions should not be included</i>): Suspected vandalism reported. Incident occurred between 10:45am – 11:00am within the BMJV central reservation work area, between junctions 7 to 5. Projectiles (steel ball bearings) directed from outside the work area on the east bound carriageway causing damage to 3no. Items of plant and a welfare unit. No persons were injured.			
<div style="display: flex; align-items: center;">  </div>			
Immediate Actions Taken: <ul style="list-style-type: none"> • Work stopped and all personnel removed from the work area. • Police informed. • Inspection of CCTV footage to assist police investigation. 			
Details of Injuries / Damage / Environmental / TM implications:	<ul style="list-style-type: none"> • Broken windows 		
Name / ID of Equipment:	<ul style="list-style-type: none"> • 22t Excavator • 5t Excavator • Telehandler • Welfare unit 		
Name of Person(s) Involved:	N/A	Age:	N/A
Their Occupation(s):	N/A		
Their Employer(s):	N/A		
D&A carried out:	N/A		
Name of Witnesses:	N/A		
Your Name:	John Phillips		

Your Contact Details:	Jl.phillips@bmjv.co.uk 07773 073 621
<p>Confirm that the report has been received and understood by a member of the SHE team / Shift Manager / Duty Manager. This can be done in person or by telephone.</p> <p>Forward a completed copy of this form to Project Director, Construction Manager and H&S Manager as soon as practical.</p>	